


R0369

Attacco rapido

Quick coupling




Ordine Nr. / Order No. Con valvola / With Valve	Ordine Nr. / Order No. Senza valvola / Without Valve	D1	D2	D3	D4	L	L1
R0369-09-0001	R0369-09-0007	6	5	17	9	59	28
R0369-09-0002	R0369-09-0008	10	6	17	9	59	28
R0369-09-0003	R0369-09-0009	10	8	22	13	65	28
R0369-09-0004	R0369-09-0010	13	9	22	13	65	28
R0369-09-0005	R0369-09-0011	16	13	31	19	96	38
R0369-09-0006	R0369-09-0012	19	13	31	19	96	38

R0370

Attacco rapido a 90°

Quick coupling 90°




Ordine Nr. / Order No. Con valvola / With Valve	Ordine Nr. / Order No. Senza valvola / Without Valve	D1	D2	D3	D4	L	L1
R0370-09-0001	R0370-09-0006	6	5	17	9	43	25.5
R0370-09-0002	R0370-09-0007	9	6	17	9	43	25.5
R0370-09-0003	R0370-09-0008	9	8	22	13	51	30
R0370-09-0004	R0370-09-0009	13	9	22	13	51	30
R0370-09-0005	R0370-09-0010	19	13	31	19	78	34

R0371

Innesto rapido filetto maschio

Male thread quick plug



Ordine Nr. Order No.	D	D1	D2	L	L1	ES. HEX.
R0371-09-0001	BSP 1/8"	6	9	24	7	11
R0371-09-0002	BSP 1/4"	6	9	26	9	14
R0371-09-0003	BSP 3/8"	6	9	26	9	17
R0371-09-0004	M10x1	6	9	24	7	11
R0371-09-0005	M14x1.5	6	9	26	9	15
R0371-09-0006	M16x1.5	6	9	26	9	17
R0371-09-0007	BSP 1/8"	9	13	24	7	14
R0371-09-0008	BSP 1/4"	9	13	26	9	14
R0371-09-0009	BSP 3/8"	9	13	26	9	17
R0371-09-0010	BSP 1/2"	9	13	24	12	22
R0371-09-0011	M10x1	9	13	24	7	14
R0371-09-0012	M14x1.5	9	13	26	9	15
R0371-09-0013	M16x1.5	9	13	26	9	17
R0371-09-0014	BSP 1/2"	13	19	47	12	22
R0371-09-0015	BSP 3/4"	13	19	51	16	27
R0371-09-0016	M24x1.5	13	19	51	16	27